




Schematic diagram of connection of injection molding machine with energy saver